Non-Conformance Report	NCR 788
Raised by: TASON LOADER Source: TRANSNORTH.	
Non-Conforming	Sheet No. \ of \
Dept./Supplier:	04.08.31
Product/Service:	Priority: HIGH
Product/Service: D206-628-01/-012	LOW
Area of Standard: Section A  Description of Non-Conformance	
QSP ASSECTION OF STATE OF STAT	P 70
QSP QSPM CRACK ORIGIONATING AT GOE BRACKET WELDMENT	. , , ,
BRACKET WELDMENT	
Documents:	
P/O	
Invoice	
W/O	•
Batch No. TSR	
Drawing	
Forward to Director, Quality A	Assurance on completion of this box
DQA: Section B: Indicate who is responsible for creating C/A, and a completion date. Section C: Indicate wh	o will verify completion of C/A.
Section B  Corrective Action  Responsible for Investigation/CA: Bill Becket	To be done by: FeR 18105
State and the state of the stat	
	onsible Due date Sign/Date
END CUSTOMER REPLACEMENT STEPS	
OF THE STEP BRACKET WELDS BEFORE	
	1546 B 04/09/01
2. HAVE CUSTOMER RETURN DAMAGED STEPS / DAN	ELLE B 04/09/01
3 FIRST KEMANJUNG STEPS IN INVENTORY ARE	
THOSEOGRAPT ANSWELLED YRIOK TO SHIPMENT ISIL	L. B. Quaren 1/ED
The state of the s	N. S. 100 2 400 1
EVALUATE DESIGN AND WELDING PARAMETERS DAVI	D 5. So stock
OF STEPS AND CLAMPS TAKE	W L. )
	r Hum
O. TOPE COMPAND TO SOR TO SUR	
<u> </u>	
Parametrica Action Burian	ault Category:
Preventive Action Required: NO YES #	Instruction Deasn.
Section C (C)	3000
Verification of C/A Responsible for Verification of CA: Responsible for Verification of CA:	1
No Verification Method Sign / Date	te [
CPON CAR #180 to resolve (3) ash	Forward to DQA on Completion of Verification
issues of all and give to	
	I IMi
total them Engineering Design	DQA: ////Y
tota than Engineering Design	DQA:
tota then inspectify Design	DQA: 1415 Date: 05/01/06

File BOX GAIZ



## DART AEROSPACE LTD 1270 Aberdeen Street Hawkesbury, Ont., K6A 1K7 Canada



INVOICE #:

14202

Page:

1

Trans North Helicopters

Ship to:

Trans North Helicopters

P.O. Box #8

115 Range Road

Whitehorse YT Y1A 5X9

Whitehorse YT Y1A 5X9

Date:

08/10/04

Terms:

0/ 0/ N30

Due: 09/09/04

PO#:

WARRANTY

Ship Via:

**FEDEX** 

FOB:

Packing Slip #:

3004373

Description

Ordered

Shipped

**Unit Price** 

Extended

Heli-Access-Step LH

Item #:

D206-628-011

1.0

1.0

0.00

0.00

Tel: Fax: (613) 632-3336 (613) 632-4443

email:

heli@dartaero.com

web:

www.dartaero.com

**GST** Registration PST/TVQ Exemption # 10127 2607 RT

GST:

0.00 0.00

Remittance of Applicable Provincial Sales Tax is the responsibility of

PST/TVQ: TOTAL:

Subtotal:

0.00 0.00

the purchaser (excl Ontario).

Amount due:

0.00

				0E N	vo. <u>30</u>	04373
		Contract Rev	view Form			
Quota	tion Date: 10/1	HG/2004.		No: _	097	<u>58</u>
Order	Date: 10 / 1	AUG /2004		RA N	o:	· .
Ship	ping Date:	1.S.A.P.		NCR	No:	
	red by: P	MSJ.	Incoming: Phone:	✓ Fa	ax: 🗸 E	mail: <u> </u>
Order	ing Company: 1/a	nsNorth	Contact: Pat	How	ell_	
Phone	e No: 1.867	668-2177	Fax: 1 58	07.6	068.3	3420.
;			Email:			·
Billing	Address:		Shipping Address:		•	•
	Some		Trans No	nth	Helico	opters.
			115 R	znice	Rea	<u>d</u>
		·	White	nov se	YT,	YIA5X
Purch	ase Order No: Wa	rranty.	IRS/ABN	No:	N	
	od of Payment:	1	it Card No:	M	<u>~</u>	
Freigl	nt: Fed Ex		Acct No :		\$ 1L	1.
			P/O Rev	,.	1	<i>V</i> =
P/U /	Acknowledgement:	~ ~ ~	170 KeV		Link	[ Diagonal ]
Qty	Part Number	Description	Batch	Disc.	List Price	Discount Price
	D266-6-28-011	Step	619467		960	NC
Notes		HARVERLE	71	· · · · · · · · · · · · · · · · · · ·	<u> </u>	.1
Notes	•	Various	7			
Quot	e/Tender Review:				•	
Inven Produ			Engineering Şervices		M or Quo \$₹\$25 000	tes/Orders (US)
VP M		Marketing:	VP Marketing:		Marketing	:
	legate ' Mi De	g. Mgr. esign Mgr.	Design Mgr:	VP DQ	Finance: _ A:	
<b>.</b> .	DO	QA:			/	
	Review:					
	legate		•			

H:\Forms\Marketing\approved forms mktg\CRF RevI

## Peggy McDonald

From: To: "Jason Loader" <jloader@eaglecopters.com>
"Peggy McDonald" <peggym@dartaero.com>

Sent:

Tuesday, August 10, 2004 11:42 AM

Subject:

RE: Emailing: crack-flightstep21

Yes. Jason

----Original Message----

From: Peggy McDonald [mailto:peggym@dartaero.com]

Sent: Tuesday, August 10, 2004 9:24 AM

To: Jason Loader

Subject: Re: Emailing: crack-flightstep21

We should sent a replacement correct????? Peggy

---- Original Message -----

From: "Jason Loader" < jloader@eaglecopters.com > To: "'Peggy McDonald'" < peggym@dartaero.com >

Sent: Tuesday, August 10, 2004 9:49 AM Subject: RE: Emailing: crack-flightstep21

- > I've sent an E-mail to Danielle to have her issue a Return Authorization
- for
- > this step
- >
- > Jason
- >
- > ----Original Message-----
- > From: Peggy McDonald [mailto:peggym@dartaero.com]
- > Sent: Monday, August 09, 2004 2:27 PM
- > To: Jason Loader
- > Subject: Re: Emailing: crack-flightstep21
- >
- > I think we should replace the step to keep the customer happy. Ask
- Danielle
- > to send a replacement step P/N D206-628-011 and issue the RA Contact
- Pat
- > Howell Tran North Helicopters.
- > Thanks
- > Peggy
- >
- > ---- Original Message -----
- > From: "Jason Loader" < <u>iloader@eaglecopters.com</u>>
- > To: "'Peggy McDonald'" <peggym@dartaero.com>
- > Sent: Monday, August 09, 2004 3:47 PM
- > Subject: RE: Emailing: crack-flightstep21

```
>> It may be easier and faster if they have access to an approved welding
> shop
>> to weld repair the crack. It looks as though the failure was due to a
weld
>> fault - crack origionates at a weld termination crater. If this is the
> case
>> then it would be a warranty issue, but it's hard to say for sure from a
>> photograph. For the relatively short life of the step, it may be best to
>> just replace the step and keep the customer happy. If you agree with me,
>> me know and I will have Danielle issue a Return Authorization.
>> Jason
>>
>> ----Original Message----
>> From: Peggy McDonald [mailto:peggym@dartaero.com]
>> Sent: Monday, August 09, 2004 1:10 PM
>> To: Jason Loader
>> Cc: Danielle Bilodeau
>> Subject: Fw: Emailing: crack-flightstep21
>>
>>
>> Hi Jason,
>> I received this email and a phone call from Pat Howell - this is a
>> of CRACKED P/N D206-628-011 shipped in May - They need a replacement
>> asap - What do you think? Should a replacment be sent out and we will
> issue
>> a Return Authorization for the cracked step.
>> If this is acceptable, can you send an email to Danielle authorizing to
> send
>> a replacement.
>>
>> Thanks
>> Peggy
>>
>> ----- Original Message -----
>> From: "Pat Howell" <phowell@tntaheli.com>
>> To: <peggym@dartaero.com>
>> Sent: Friday, August 06, 2004 2:07 PM
>> Subject: Emailing: crack-flightstep21
>>
>>
```

Non-Conform	N	NCR <b>7</b> {	38		
Raised by: TASON LOADER	Source: TEANS	JORTH.	٩	Sheet No.	\ of \
Non-Conforming				Date:	
Dept./Supplier:				٥4.0	8.31
Product/Service: D206-628-	011/-012			Priority:	HIGH LOW
Area of Standard: Section A  QSI  Description of M	Ion Conform			Aveto	
	ion-Conformance		200	70	
QSPM CRACK C	RIGIONATING WELDMEN"	SAI GO	Kanpar Kanpar	10	
BRACKET	WELDMEN	7			
Documents:					
P/O					
Invoice W/O					
Batch No.					
TSR					
Drawing					
DQA: Section B: Indicate who is responsible for creating		to Director, Qualit			
Section B	OFF, and a completion date. Se	ecuon O. moroace	WIIO WIII VG	my completion	OI CA.
Corrective Action Responsible for In	vestigation/CA:		To b	oe done by:	
No Initial Action D	<u>escription</u>	R	esponsible	Due date	Sign/Date
- SEND CUSTOMER RE					
FULLIFE A THOROU					
SHIPMENT	ET WELDS BEFORE		ANICIZ	B 406 11/04	
- HAVE CUSTOMER RET	TIRN DAMAGED &			B AUG 11/04	
-ELEURE REMANDING.		DRY ARE		2 /12 (2 - 7 - 7	
THOROUGHLY TUSAGO		IPMENT B	ILL-B	56013/04	
<i>                                  </i>		COX I'	1.1.0	00-011	
EVALUATE DESIGN AND			<del>XIV. 5.</del> Wid s.	OCT 4/04	
OF STEPS AND CLA	us PS	177	HON L.		
-IMPLEMENT NEW STE	I MOUNT DES	Cal			
TISTO STEPS		13	ici B	- Jan 3/01	
			Fault C	Category:	
Preventive Action Required: NO YE	s #		lauk	Jalegoly.	
Section C	-1- 61/1P		L	· · · · · · · · · · · · · · · · · · ·	
Actividation of OW	ble for Verification of CA:		· · · · · · · · · · · · · · · · · · ·		
No Verification Method		Sign	Date	C	
				forward to DQA on Completion of Vorify	
				DQA:	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			Date:	·
QA Purposes only	N/C	Closed		ate	
H:forms\Quality Assurance\approved QA\NCR rev C	14/0	DIVOUY		uic	

	nance Report		NCR T	36
Raised by: TASON LOADER	Source: TRANSNORTH		Sheet No.	\ of \
Non-Conforming Dept./Supplier:			Date:	_
Draduct/Comica.			Priority:	HIGH
D206-628	-011/-012			LOW
Area of Standard: Section A  QSI Description of	Non-Conformance			
QSP QSPM (LACK	ORIGIONATING AT	STEP	70	
RPACKET	ORIGIONATING ATO			
Documents:				
P/O				
Invoice W/O				
Batch No. TSR				
Drawing				
	Forward to Director, G	)ualitv Assurai	nce on completic	on of this box
DQA: Section B: Indicate who is responsible for creating Section B				
	Investigation/CA:	To	be done by: _	
No Initial Action	Description	Responsibl	e Due date	Sign/Date
1 7t- SEND CUSTOMER R	CEPLACEMENT STEPS UGH VISUAL INSECTION			
OF THE STEP BRACE	KET WELDS BEFORE			
2 19 HAVE CUSTOMER RE	ETURN DAMAGED STEPS		B AUG 11/04 B. AUG 11/04	
3 Th-ENSURE REMAINING	STEPS IN INVENTORY ARE			
4 4 L-CUT BRACKET SECTION	TED PRIOR TO SHIPMENT US, OF STEP (ASPROXI"	BILL &	SEPT 8/04	
ETHER SIDE OF BRACE	(ET) SEND SECTIONS TO EAGLE		GEPT 16/04	WL _
OF STEPS AND G	D WELDING PARAMETERS? AMPS.	DAVID S	· Oct 4/04	11 05 02 0
6 76 TIMPLEMENT NEW 57	EP MOUNT DESIGN	BILLE	21/1/2	
4518 37617		DICC F	S. JANSYD	
Preventive Action Required: NO	YES #	Fault	Category:	L
Section C				
Verification of C/A  No Verification Metho	sible for Verification of CA:	Doto I		-
TO VOIMORION MELTIC	d Sign	Date	Forward to DQA on Completion of Verifi	
			DQA:	
			Date:	
QA Purposes only H:forms\Quality Assurance\approved QA\NCR rev C	N/C Closed		Date	



## **Transnorth**

				Printed of	on:	July 06, 2011
<b>愛いり、食料</b>						
Number	Status		Owner			Raised Date
NCR788	Closed	]1	Beckett, Bill			8/31/2004
Source	Standard					Target Date
Transnorth						9/1/2004
Raised By Person	Severity	Rais Supr	ed Against (Departmo olier)	ent or	Fault Cat	egory
Loader, Jason (508)			neering\Design			
Audit	1	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
<b>Details</b> Cracks origionating at	step to bracket weldmer	ıt.				
Process			Product Service			
			D206-628\D206-628	B-011/-01	2	
Document		· · · · · · · · · · · · · · · · · · ·		Root	Cause	
				Engin	eering\Desi	gn
Closed By	Closed Date	Resolution				
Beckett, Bill	1/6/2005	Warranty				
· · · · · · · · · · · · · · · · · · ·	Jan San San San San	Ž* - *				
Target Date	Owner		Closed Date	Clos	ed By	

· 1978年1月2日 - 1987年1月2日 - 1987年1月1日 - 198	A STATE OF THE STA			
Target Date	Owner	Closed Date	Closed By	
9/1/2004	Beckett, Bill	9/1/2004	Beckett, Bill	
Details				

1. Send customer replacement steps. Ensure a thourough visual inspecton of the step bracket welds before shipment. Have customer return damaged steps R#3172. Ensure remaining steps in inventory are thoroughly inspected prior to shipment.3. Cut bracket sections of step (approx 1" eitherside of bracket) send sections to Eagle. Evaluate design and welding parameters of steps and clamps.

everativ <b>e</b> ji			
Number	Owner	Target Date	Completed Date
Details		Response	
· · · · · · · · · · · · · · · · · · ·		<u> </u>	

A MICELLA COMMENT								
Target Date	Owner	Closed Date	Closed By					
9/1/2004	Trepanier, Dale (551)	1/6/2005	Trepanier, Dale (551)					
Details								
Open CAR#180 to res	Open CAR#180 to resolve issue and gave to Engineering Design.							

Number	Owner	Target Date	Completed Date		
Details		Response	Response		